



THE TEN COMMANDMENTS OF TESTING

1. Draw and test representative samples.
2. Know, follow, and understand test procedures and test interferences.
3. Calibrate meters – Keep batteries and reagents in date.
4. Use clean glassware – Rinse between tests.
5. Use proper sample sizes.
6. Know multipliers, conversions, control ranges, and expected test results.
7. Test in a well-lit area.
8. Have established, in-plant testing program – Keep operators trained.
9. Keep complete test logs.
10. Take corrective action and document changes.



Innovative Solutions Provider